



JANGRO Product Guide





Sovereign Floor Gloss Restorer High Solids BD235-5





- 


1 Put on PPE
- 

2 Place safety signs.
- 

3 Sweep floor.
- 

4 Dilute 1 part per 50 parts of cold water.
- 

5 Mop solution onto floor.
- 

6 Leave for 30 minutes.
- 

7 Once surface is dry, remove safety signs.

Health & Safety
Please refer to relevant
COSHH Sheet.